

Ecessa Firmware Release Notes

Version: 10.7.2

Release: 2017.05.19

Revision 1.0: 2017.05.19

Improvements

SIP Proxy

- **The SIP Proxy needs the ability to send to the original destination of the SIP packet that is received on the LAN side of the proxy instead of determining the SIP destination based on the RFC 3261 specification**

[Additional Information](#)

The option 'Sending SIP to the original destination' is useful when the SIP device on the LAN is configured with a host name outbound proxy. If the SIP device is configured with a IP based outbound proxy then configuring an outbound proxy on the Ecessa is sufficient.

- **The SIP proxy needs an option to source NAT inbound SIP requests**

[Additional Information](#)

This option should be enabled if the devices on the LAN side are configured to validate the SIP source IP.

DNS

- **An SRV record which is entered with an underscore in the protocol or service will cause duplicate underscores in the zone file**

[Additional Information](#)

This causes DNS to function improperly on the device.

Fixes

WAN

- **Old DHCP addresses may silently remain on the device after a new one is received**

[Additional Information](#)

This can happen in two cases. One is Hardware Failover is disabled from an enabled state. The other is a cable is unplugged and the DHCP lease is allowed to expire.

- **Usage of PPPoE WANs can cause the system to restart**

WAN Virtualization

- **When loading a configuration, Uplink and Downlink speeds for a WAN Virtualization site may not load properly**

[Additional Information](#)

This occurs when the remote site has a higher maximum WAN speed than is allowable on the device.

- **WAN Virtualization configurations where tunnels have high packet loss and the tunnel testing parameters are set high can cause the tunnel to bounce more often than the testing parameters**

[Workaround](#)

Make sure that the testing parameters for a tunnel have a lower timeout (less than 5 seconds) and instead increase the number of tests to match your requirements.

- **Activating the WAN Virtualization advanced site Web UI page can display the wrong tunnel encryption selections**

[Additional Information](#)

The tunnel encryption selections are correct but are initially displayed incorrectly. Navigating again to the page will display the correct selections.

VPN

- **When multiple IPsec IKEv1 VPNs are enabled with a remote identifier configured, The VPNs may not connect**

[Additional Information](#)

This happens because the pre-shared-secret is chosen incorrectly. This issue is not present when using an IKEv2 type VPN.

- **A VPN IPsec VTI security association can get into a state where it reports as UP traffic will not pass**

- **When remote connection from an IPsec VPN is closed, the VPN will not reinitiate the connection**

[Additional Information](#)

If the remote side of a VPN has an inactivity timeout, it will close the connection for one or more subnet combinations. This will stop all traffic for that given subnet combination. Ability to start IPsec VPN for On Demand traffic has been added. With the 'On Demand' start option, when interesting traffic has been seen, the VPN will reinitiate the connection. Dead Peer Detection number of tests and timeout interval options have been added as well. This allows for configuration of DPD to allow the sites to match in detection time. A DPD mismatch can lead to incorrect status as well as connectivity issues.

- **Site-to-site VPN may attempt to use a WAN that is down**

[Additional Information](#)

This VPN will not try to recover even if failover testing is enabled, and will not connect until the WAN comes back up.

- **A VTI VPN on an Ecessa device which is behind NAT will not be able to connect**

[Additional Information](#)

A VTI VPN on the Ecessa device will show as UP but the traffic will not pass through it. This is only a problem if one of the Ecessa devices is behind NAT.

- **WAN graphs will report double the expected throughput for encrypted WAN Virtualization receive traffic**

[Additional Information](#)

For transport type VPN connections, like WAN Virtualization uses, the traffic gets counted both encrypted and again after decryption.

SIP Proxy

- **SIP phone Busy Lamp Field soft keys may not display properly when UDP SIP messages are processed by the Ecessa SIP Proxy**

- **The Ecessa SIP proxy can become unresponsive when a call that is establishing contains multiple SDP media sections in the SIP signaling**

- **The Ecessa SIP proxy does not display statistics correctly for faxes that are proxied**

[Additional Information](#)

This refers to the address information that is shown in the advanced section of the VoIP call

- **SIP proxy handling of SIP Cancel requests may fail**

- **Phones that modify our SIP VIA headers can cause SIP response packets to be dropped**

- **SIP proxy configurations which use domain authentication can cause the system to crash when a call needs to fail over more than once**

- **SIP Proxy does not start properly after multiple Hardware Failovers**

- **Changing SIP Proxy port range can result in old rules being left in place**

- **The Ecessa SIP proxy can become unresponsive when a high RTP port is used to establish a call**

- **SIP Proxy process can unexpectedly restart during initialization**

ACL

- If the option 'Enable accessing Idle Service via Active Device (WAN Only)' is enabled for the Hardware Failover feature then traffic destined to the LAN which uses the same ports as management services for the Ecessa device will be rejected

Workaround

Disable the following option on the Hardware Failover page:

Hardware Failover -> Advanced -> Enable accessing Idle Service via Active Device (WAN Only). If you need to access the IDLE device then fill in an idle IP address instead of using this feature

Configuration

- Adding a site to the Ecessa Insight may report as successful while the site will show DOWN in the dashboard even though the live site is UP

Additional Information

This can also cause new configurations to not be sent to Ecessa Insight for sites that were configured in the past.

Diagnostics

- Web Diagnostics ping timeout not working as expected

Additional Information

The diagnostics ping utility sends multiple ICMP Requests until it receives a reply within the timeout specified. The expected behavior is to only send 1 ICMP echo request per test.

- Diagnostics speed-test upload can fail if an aspx server is chosen

DNS

- Using CLI to modify DNS records does not update zones properly

Additional Information

This bug does not effect modifying DNS Records via the web interface.

- Within DNS domain configuration, Simple Host Records and Load Balanced Host Records mail entry should not be a dropdown menu

Additional Information

The 'Mail Entry' drop-down is changed to a checkbox and renamed 'MX Record.'

- SRV record hostname error message is unclear

Certificates

- Email alerts are not sent for expiring Self CA certificates after a certificate is renewed

Statistics

- Session statistics for UDP sessions can show much higher usage than expected

Additional Information

The following graphs are affected: Top IPs To/From, Top Services, Top Protocols.

PPPoE

- A configured PPPoE server may provide addresses outside the associated LAN subnet
- A configured PPPoE server uses an MTU of 1500 even if it is configured for a different value

SNMP

- Ecessa SNMP MIB file may not be accepted by SNMP monitoring programs due to syntax errors

Additional Information

This affects at least Paessler PRTG monitoring tool

Workaround

If you are unable to upgrade to the version where this is fixed then contact Technical Support and they can provide you with the updated SNMP MIB file, which can then be imported into the monitoring program that is being used

Known Issues

System

- **Ports can become disabled on legacy 600 product (7568c) when pulling a cable during traffic flow**

Additional Information

Ports can become disabled on legacy 600 family of products (7568c) when pulling cables during traffic flow. The device will have to be manually rebooted in order to get the port into a working state.

Workaround

Reboot the device.

WAN

- **The DHCP service can stop unexpectedly**

Additional Information

The DHCP service stopping will cause DHCP WAN lines to miss IP Address updates.

Workaround

If a DHCP WAN does not properly update its IP Address then reboot the device.

- **When a DHCP WAN is given a very short lease time by the modem the Ecessa device can become unresponsive**

Additional Information

The duration of a lease is typically at least several hours. When the duration of the lease is less than a minute this problem can occur.

Workaround

Verify that the ISP modem is providing the DHCP WAN with a proper lease time.

WAN Virtualization

- **Adding an encrypted WAN Virtualization site using the CLI may not work as expected**

Additional Information

Using the CLI to add an encrypted WAN Virtualization site, and setting global WAN Virtualization options at the same time, will result in no VPN entry being created for the site.

Workaround

Using the CLI, commit global WAN Virtualization changes separately from committing the added site. Or add the site using the Web Interface.

- **Enabling WAN Virtualization encryption using the CLI without specifying a VPN name will create an IPSec VPN security association entry which has no name**

Additional Information

Modifying an unencrypted WAN Virtualization site by using the CLI to enable encryption, without specifying a vpn-name, will create an IPSec VPN Security Association entry which has no name. The user will then have no way to delete the entry.

Workaround

Make sure to specify the 'vpn-name' in the CLI command, or use the Web GUI to enable encryption for WAN Virtualization sites.

- **WAN Virtualization which is using non base IP addresses can not route as expected when a static route is in place which applies to all traffic**

Additional Information

WAN Virtualization feature which is setup to use non base IP addresses can have issues when there is a static route that is in place which is setup to apply to all traffic.

Workaround

There are several ways to address this issue:

1. If possible use the base IP addresses for WAN Virtualization.
2. Change the static route so that it only applies to the traffic that is necessary.

- **WAN Virtualization hub location cannot have a site number that is greater than 127**

Additional Information

When a WAN Virtualization site is created, the hub site (which is defined as the site with the lower site ID number) must be 127 or lower. If the value is greater than 127 then the associated site will be unable to connect. This does not affect the remote site IDs, which can be greater than 127. This does not affect the total number of sites allowed.

Workaround

Set the associated hub site to have a lower site number.

VPN

- **IPSec VPN failover test point type 'Manual IP Configuration' does not work as expected**

Additional Information

The IPSec VPN failover test point type 'Manual IP Configuration' does not work. The test pings to the far LAN should get source NAT'ed to the local LAN IP to get sent through the VPN. Instead, they get sent out a WAN.

- **IPSec VPN Failback option does not work as expected**

Additional Information

With IPSec VPN Failback enabled it does not fail back to the preferred path when that path comes back up.

Hardware Failover

- **Using Hardware Failover with high traffic throughput can cause excessive loading of the device**

Additional Information

Hardware Failover is by default stateful, and a very high number of TCP sessions can cause excessive loading of the device.

Workaround

If a Hardware Failover device becomes slow to respond, turn off the stateful option in Hardware Failover using the following CLI command: 'hwfo set stateful disable; commit save'

Virtual Product

- **Virtual Product may boot slowly**

Additional Information

Slow boot sequence has been observed. Infrequently the Virtual Product will take around four minutes to boot. Upon boot everything functions normally.

Workaround

Force reset the device.

SIP Proxy

- **Phone calls made within a short time after enabling the VoIP feature may not choose the Primary WAN**

Workaround

Wait at least 10 seconds after initially enabling the VoIP feature before making phone calls.

DNS

- **DNS Reverse Zone may not work correctly for load-balanced hosts**

Additional Information

DNS Reverse Zone information for load-balanced hosts may be set up incorrectly with PTR option.

Workaround

Remove the load-balanced host, activate changes, then add the load-balanced host again.

LCD

- **The LCD display can become stuck and not display new information when keys are pressed**

Workaround

Reboot the device.

Aliases

- **Using the CLI to create an alias with multiple addresses will reorder the addresses and remove duplicates, making the alias unusable for firewall forwarding rules**

Additional Information

If creating aliases to use for firewall WAN to LAN one-to-one forwarding rules, the CLI will not create them properly since it reorders them and deletes duplicates.

Workaround

Use the Web GUI to create aliases where the order of the addresses, and preservation of duplicates is important.