

Ecessa Firmware Release Notes

Version: 10.7.3

Release: 2018.02.12

Revision 1.0: 2018.02.12

Improvements

System

- **Add the ability to push a system snapshot to Ecessa using the web interface**

[Additional Information](#)

In the web interface go to Utilities->Get/Set Configuration->Snapshot tab.

VPN

- **Added remote endpoint testing options for active IPSec VPN monitoring in the CLI and web interface**

- **VPN Monitoring is now more efficient in monitoring security associations**

[Additional Information](#)

Site-to-Site security associations which were configured in Active mode will choose a failover path in one interval compared to multiple in previous releases.

Site-to-Site security associations which were configured as on-demand now support failback functionality if the first local WAN end point becomes available

Static Routes

- **Add an option which allows static route sessions to not be disrupted during configuration activation**

DNS

- **Implement DNS resolver cache system for resolving FQDN's**

[Additional Information](#)

Resolve host names used by configured features and cache them internally for faster look-ups, and to prevent long delays when name servers are unreachable.

Monitoring

- **Ecessa Insight passive monitoring configuration is now available via the CLI**

Diagnostics

- **Diagnostics iperf now has the ability to set UDP bandwidth**

Users

- **The web interface now informs the user that user account information is not sent to the idle hardware failover device during replication**

Fixes

WAN

- **Failover type static routes may not have behaved as expected after activating changes or loading a configuration**

[Additional Information](#)

Failover type static routes are expected to revert back to configured WAN routes after activating static route changes.

WAN Virtualization

- Encrypted small packets received over WAN Virtualization can become reordered

VPN

- Deleting a WAN for an On Demand type VPN can cause the VPN to not come up
- Old IPsec VPN VTI devices may not get removed, possibly preventing successful re-connection
- IPsec L2TP clients may not be able to re-connect if they have a different IP address than the last time they connected
- IPsec VPN Failback option does not work as expected

Additional Information

With IPsec VPN Failback enabled it does not fail back to the preferred path when that path comes back up.

Hardware Failover

- The idle hardware failover unit can get in a state where it can't communicate with the active unit

Additional Information

Idle unit may not get fully configured if hardware failover is disabled and then re-enabled, resulting in the idle unit appearing down from the perspective of the active unit.

Workaround

Once in this state, disable then re-enable hardware failover on the idle unit

SIP Proxy

- SIP Proxy registrations can become unbalanced across WAN's
- Multiple registrations for the same SIP user from different locations should use different public SIP ports

Configuration

- Loading a configuration with different WAN names could result in a failure to load

QoS

- QoS applied to WAN Virtualization sites may cause packet loss when packet throughput rates are high

Additional Information

QoS classes using fifo type queues, when applied to WAN Virtualization sites, create queues that have a very small size limit. Under moderate to heavy packet rates these queues can be overrun and result in packets being dropped.

Workaround

Use 'fair' type queues for QoS classes on virtual devices (WAN Virtualization and VLAN's) when traffic associated with those classes may be small packets or flow at a high packet rate.

DNS

- The GUI "IP Address or Hostname" field for simple host records in a DNS domain will handle only up to 63 characters
- DNS simple host records do not accept underscores where an FQDN is accepted
- DNS zone information may not be properly updated after a WAN status change

Workaround

Go to the Authoritative DNS page and disable DNS globally. Once the page is activated re-enable DNS globally.

- Use DNS resolver cache for aliases containing FQDN's to prevent long delays trying to resolve when the name servers are not accessible

Monitoring

- **Devices connected to Ecessa Insight can create duplicate monitoring alerts**

Diagnostics

- **There is no way to display and stop diagnostics iperf servers via the CLI**

Aliases

- **Fully qualified domain name used in an alias will get overwritten with resolved IPs**

Additional Information

This happens when the Static Route page is activated, on boot, on config change, or can happen on a WAN status change.

Known Issues

System

- **Ports can become disabled on legacy 600 product (7568c) when pulling a cable during traffic flow**

Additional Information

Ports can become disabled on legacy 600 family of products (7568c) when pulling cables during traffic flow. The device will have to be manually rebooted in order to get the port into a working state.

Workaround

Reboot the device.

WAN

- **The DHCP service can stop unexpectedly**

Additional Information

The DHCP service stopping will cause DHCP WAN lines to miss IP Address updates.

Workaround

If a DHCP WAN does not properly update its IP Address then reboot the device.

- **When a DHCP WAN is given a very short lease time by the modem the Ecessa device can become unresponsive**

Additional Information

The duration of a lease is typically at least several hours. When the duration of the lease is less than a minute this problem can occur.

Workaround

Verify that the ISP modem is providing the DHCP WAN with a proper lease time.

WAN Virtualization

- **When a device is running a configuration which has WAN Virtualization sites and loads a configuration which does not have WAN Virtualization sites configured the device software may restart**

Additional Information

This is only a factor if the device has a product key which supports less WAN Virtualization sites then the configuration that is currently running

- **Adding an encrypted WAN Virtualization site using the CLI may not work as expected**

Additional Information

Using the CLI to add an encrypted WAN Virtualization site, and setting global WAN Virtualization options at the same time, will result in no VPN entry being created for the site.

Workaround

Using the CLI, commit global WAN Virtualization changes separately from committing the added site. Alternatively, add the site using the web interface.

- **Enabling WAN Virtualization encryption using the CLI without specifying a VPN name will create an IPSec VPN entry with no name**

Additional Information

Once an entry with no name is created, the user will then have no way to delete the entry.

Workaround

Make sure to specify the 'vpn-name' in the CLI command, or use the web interface to enable encryption for WAN Virtualization sites.

- **WAN Virtualization which is using non base IP addresses can not route as expected when a static route is in place which applies to all traffic**

Additional Information

WAN Virtualization feature which is setup to use non base IP addresses can have issues when there is a static route that is in place which is setup to apply to all traffic.

Workaround

There are several ways to address this issue:

1. If possible use the base IP addresses for WAN Virtualization.
2. Change the static route so that it only applies to the traffic that is necessary.

- **WAN Virtualization hub location cannot have a site number that is greater than 127**

Additional Information

When a WAN Virtualization site is created, the hub site (which is defined as the site with the lower site ID number) must be 127 or lower. If the value is greater than 127 then the associated site will be unable to connect. This does not affect the remote site IDs, which can be greater than 127. This does not affect the total number of sites allowed.

Workaround

Set the associated hub site to have a lower site number.

Hardware Failover

- **Using Hardware Failover with high traffic throughput can cause excessive loading of the device**

Additional Information

Hardware Failover is by default stateful, and a very high number of TCP sessions can cause excessive loading of the device.

Workaround

If a Hardware Failover device becomes slow to respond, turn off the stateful option in Hardware Failover using the following CLI command: 'hwfo set stateful disable; commit save'

Virtual Product

- **Virtual Product may boot slowly**

Additional Information

Slow boot sequence has been observed. Infrequently the Virtual Product will take around four minutes to boot. Upon boot everything functions normally.

Workaround

Force reset the device.

SIP Proxy

- **Phone calls made within a short time after enabling the VoIP feature may not choose the Primary WAN**

Workaround

Wait at least 10 seconds after initially enabling the VoIP feature before making phone calls.

Static Routes

- **Failback static route over WAN Virtualization doesn't fail back after failing over to a WAN**

DNS

- **DNS Reverse Zone may not work correctly for load-balanced hosts**

Additional Information

DNS Reverse Zone information for load-balanced hosts may be set up incorrectly with PTR option.

Workaround

Remove the load-balanced host, activate changes, then add the load-balanced host again.

Aliases

- **Using the CLI to create an alias with multiple addresses will reorder the addresses and remove duplicates, making the alias unusable for firewall forwarding rules**

Additional Information

If creating aliases to use for firewall WAN to LAN one-to-one forwarding rules, the CLI will not create them properly.

Workaround

Use the web interface to create aliases where the order of the addresses, and preservation of duplicates is important.

LCD

- **The LCD display can become stuck and not display new information when keys are pressed**

Workaround

Reboot the device.