

Ecessa Firmware Release Notes

Version: 10.7.4

Release: 2018.04.30

Revision 1.0: 2018.04.30

New Features

System

- Ability to set network interface receive and transmit ring buffers

Improvements

VPN

- The self certificate authority can be configured to use sha1 message digest in addition to md5
[Additional Information](#)
Customers that update to this version will still have md5 as their certificate authority message digest until this is changed. A user that creates a new certificate authority will be able to choose the digest, with the first option being sha1.

Fixes

WAN Virtualization

- WAN Virtualization traffic can cause the device to lock up and reboot

VPN

- Performing CLI certificate actions can cause the SSL security associations to get removed from the configuration
[Workaround](#)
Before performing the certificate action in the CLI first run the command vpn show
- IPSec VPN connections with active testing appear to be up when all remote endpoints are down
- IPSec VPN connections do not get re-started after WAN changes are made, or after a WAN gets a new IP address
- IPSec VPN monitoring can stop after WAN changes are made, or after a WAN gets a new IP address

Certificates

- Adding multiple self CA certificates in the command line interfaces will cause the certificates to show up with blank information
- Adding a self CA certificate with the option to add the certificate to the main list, via the command line interface, will cause the certificate in the main list to not be present
- Creating self CA certificates via the command line interface causes the certificates not to be created correctly
[Additional Information](#)
After the certificates are created incorrectly they will not show creation or expiration dates
[Workaround](#)
Use the GUI to create self CA certificates instead of the CLI

Reports

- Email reports from the live device have links which do not work

Known Issues

System

- **Ports can become disabled on legacy 600 product (7568c) when pulling a cable during traffic flow**

Additional Information

Ports can become disabled on legacy 600 family of products (7568c) when pulling cables during traffic flow. The device will have to be manually rebooted in order to get the port into a working state.

Workaround

Reboot the device.

WAN

- **Creating a WAN using the CLI, with an alias of 24 characters, causes a software restart**

- **The DHCP service can stop unexpectedly**

Additional Information

The DHCP service stopping will cause DHCP WAN lines to miss IP Address updates.

Workaround

If a DHCP WAN does not properly update its IP Address then reboot the device.

- **When a DHCP WAN is given a very short lease time by the modem the Ecessa device can become unresponsive**

Additional Information

The duration of a lease is typically at least several hours. When the duration of the lease is less than a minute this problem can occur.

Workaround

Verify that the ISP modem is providing the DHCP WAN with a proper lease time.

WAN Virtualization

- **Creating a WAN Virtualization site with a name longer than 22 characters causes a software restart**

- **When a device is running a configuration which has WAN Virtualization sites and loads a configuration which does not have WAN Virtualization sites configured the device software may restart**

Additional Information

This is only a factor if the device has a product key which supports less WAN Virtualization sites then the configuration that is currently running

- **Adding an encrypted WAN Virtualization site using the CLI may not work as expected**

Additional Information

Using the CLI to add an encrypted WAN Virtualization site, and setting global WAN Virtualization options at the same time, will result in no VPN entry being created for the site.

Workaround

Using the CLI, commit global WAN Virtualization changes separately from committing the added site. Alternatively, add the site using the web interface.

- **Enabling WAN Virtualization encryption using the CLI without specifying a VPN name will create an IPsec VPN entry with no name**

Additional Information

Once an entry with no name is created, the user will then have no way to delete the entry.

Workaround

Make sure to specify the 'vpn-name' in the CLI command, or use the web interface to enable encryption for WAN Virtualization sites.

- **WAN Virtualization which is using non base IP addresses can not route as expected when a static route is in place which applies to all traffic**

Additional Information

WAN Virtualization feature which is setup to use non base IP addresses can have issues when there is a static route that is in place which is setup to apply to all traffic.

Workaround

There are several ways to address this issue:

1. If possible use the base IP addresses for WAN Virtualization.
2. Change the static route so that it only applies to the traffic that is necessary.

● **WAN Virtualization hub location cannot have a site number that is greater than 127**

[Additional Information](#)

When a WAN Virtualization site is created, the hub site (which is defined as the site with the lower site ID number) must be 127 or lower. If the value is greater than 127 then the associated site will be unable to connect. This does not affect the remote site IDs, which can be greater than 127. This does not affect the total number of sites allowed.

[Workaround](#)

Set the associated hub site to have a lower site number.

Hardware Failover

● **Using Hardware Failover with high traffic throughput can cause excessive loading of the device**

[Additional Information](#)

Hardware Failover is by default stateful, and a very high number of TCP sessions can cause excessive loading of the device.

[Workaround](#)

If a Hardware Failover device becomes slow to respond, turn off the stateful option in Hardware Failover using the following CLI command: 'hwfo set stateful disable; commit save'

Virtual Product

● **Virtual Product may boot slowly**

[Additional Information](#)

Slow boot sequence has been observed. Infrequently the Virtual Product will take around four minutes to boot. Upon boot everything functions normally.

[Workaround](#)

Force reset the device.

SIP Proxy

● **Phone calls made within a short time after enabling the VoIP feature may not choose the Primary WAN**

[Workaround](#)

Wait at least 10 seconds after initially enabling the VoIP feature before making phone calls.

LCD

● **The LCD display can become stuck and not display new information when keys are pressed**

[Workaround](#)

Reboot the device.

Aliases

● **Using the CLI to create an alias with multiple addresses will reorder the addresses and remove duplicates, making the alias unusable for firewall forwarding rules**

[Additional Information](#)

If creating aliases to use for firewall WAN to LAN one-to-one forwarding rules, the CLI will not create them properly.

[Workaround](#)

Use the web interface to create aliases where the order of the addresses, and preservation of duplicates is important.

DNS

● **DNS Reverse Zone may not work correctly for load-balanced hosts**

[Additional Information](#)

DNS Reverse Zone information for load-balanced hosts may be set up incorrectly with PTR option.

Workaround

Remove the load-balanced host, activate changes, then add the load-balanced host again.

Static Routes

- **Failback static route over WAN Virtualization doesn't fail back after failing over to a WAN**