Ecessa Firmware Release Notes

Version: 11.2.1 Release: 2020.06.25 Revision 1.1: 2020.06.25

New Features

Hardware

Support for new hardware NCA-1513A

Improvements

WAN Virtualization

• Loading a WAN Virtualization site configuration GUI page will now load the Basic configuration tab if the site does not have tunnels

Fixes

WAN Virtualization

• Activating changes on a WAN Virtualization site configuration GUI page always loads the Monitoring tab

VPN

● Connecting to L2TP VPNs may require multiple attempts before the L2TP VPN is fully established and passing traffic Workaround

If the device is only being used for VPN connectivity then downgrading to 10.7.5 will fix the issue. If the device is also being used for WAN Virtualization then update to the latest recommended version.

Date

• Incorrect timezones are displayed on the device Additional Information

It is recommended that you verify that your system timezone is correct after updating to this version. If it is not correct, change the system timezone in the CLI or GUI.

Static Routes

● Static route internal route display can show the wrong number of routes for L2TP remote clients

Additional Information

For every L2TP client that connects there is an entry for the remote address. With this issue there will be duplicate entries shown

Bond

Bonded interfaces do not get IP addresses

Performance

• Traffic with small packets caused performance issues Additional Information

The following is the type of performance issues that could be seen:

- * Higher than expected latency on the network.
- * Unexpected drops on the LAN side interfaces

Users

● User accounts that are created outside of the default users that have 'Superuser' option enabled will not be able to log in after an update from 10.7.7 to 11.1.1 or higher

Additional Information

The default users are root, admin, and user