

Ecessa Firmware Release Notes

Version: 11.1.2

Release: 2020.06.22

Revision 1.0: 2020.06.22

Fixes

VPN

- **Connecting to L2TP VPNs may require multiple attempts before the L2TP VPN is fully established and passing traffic**

[Workaround](#)

If the device is only being used for VPN connectivity then downgrading to 10.7.5 will fix the issue. If the device is also being used for WAN Virtualization then update to the latest recommended version.

Date

- **Incorrect timezones are displayed on the device**

[Additional Information](#)

It is recommended that you verify that your system timezone is correct after updating to this version. If it is not correct, change the system timezone in the CLI or GUI.

Static Routes

- **Static route internal route display can show the wrong number of routes for L2TP remote clients**

[Additional Information](#)

For every L2TP client that connects there is an entry for the remote address. With this issue there will be duplicate entries shown

Bond

- **Bonded interfaces do not get IP addresses**

Performance

- **Traffic with small packets caused performance issues**

[Additional Information](#)

The following is the type of performance issues that could be seen:

- * Higher than expected latency on the network.
- * Unexpected drops on the LAN side interfaces

Users

- **User accounts that are created outside of the default users that have 'Superuser' option enabled will not be able to log in after an update from 10.7.7 to 11.1.1 or higher**

[Additional Information](#)

The default users are root, admin, and user